



MKS 50-1000
Absolute
pressure sensor



- 1 = ground
 - 2 = signal
 - 3 = + 5V
- 0,5 bar @ 0,5 V
9,0 bar @ 4,5 V



MKS Autobusiness
Jääkärikatu 7 A 2
FIN 00150 Helsinki

marko@mksautobusiness.fi
www.mksautobusiness.fi